




Capitol Welders Supply, Inc.
51111 Choctaw Drive
Baton Rouge, La.
800-826-9268

Automatic Welding Oscillator



Oscillator Pic.jpg

Power Requirements:

115 Volt / 60HZ

Oscillator Control Functions:

- 1. Weave Speed- Pwr. On/Off
- 2. Weave Width 3" Max.
- 3. Rolls Speed Fwd./ Rev.
- 4. Positioner Speed Fwd./Rev.
- 5. Wire Speed (Dual)
- 6. Power Source Voltage Control

Shipping Weight.....63 Lbs